



# TECH CENTER VIDEOS

THIS IS A CRITICAL ENGINE REPAIR WITH SIGNIFICANT LABOR TIME.  
WATCH A SHORT VIDEO FOR INSTRUCTIONS ON YOUR SPECIFIC REPAIR.

**SAVE TIME ♦ SAVE MONEY ♦ REDUCE COMEBACKS**

| THUMBNAIL                                                                                            | VEHICLE PLATFORM                          | ENGINE              | KIT FAMILY       | LENGTH | QR CODE |
|------------------------------------------------------------------------------------------------------|-------------------------------------------|---------------------|------------------|--------|---------|
| <p>CLOYES 9-0397SA</p> <p><b>Chrysler 2.7L</b><br/>TIMING CHAIN REPLACEMENT</p>                      | <b>CHRYSLER</b><br>DODGE                  | 2.7L                | 9-0397<br>9-0707 | 9:38   |         |
| <p>CLOYES 9-0393SF</p> <p><b>Chrysler 4.7L</b><br/>TIMING CHAIN REPLACEMENT</p>                      | <b>CHRYSLER</b><br>DODGE ♦ JEEP<br>RAM    | 3.7L ♦ 4.7L         | 9-0393           | 10:49  |         |
| <p>CLOYES 9-0398SB</p> <p><b>Ford 4.0L</b><br/>TIMING CHAIN REPLACEMENT</p>                          | <b>FORD</b><br>MERCURY ♦ MAZDA            | 4.0L                | 9-0398           | 12:00  |         |
| <p>CLOYES 9-4226S &amp; 9-0738S</p> <p><b>Ford 3.5/3.7L DOHC V6</b><br/>TIMING CHAIN REPLACEMENT</p> | <b>FORD</b><br>LINCOLN ♦ MAZDA<br>MERCURY | 3.3L<br>3.5L ♦ 3.7L | 9-4226<br>9-0738 | 10:27  |         |
| <p>CLOYES 9-0391SB</p> <p><b>Ford 5.4L</b><br/>TIMING CHAIN REPLACEMENT</p>                          | <b>FORD</b><br>LINCOLN ♦ MERCURY          | 4.6L<br>5.4L ♦ 6.8L | 9-0387<br>9-0391 | 8:50   |         |
| <p>CLOYES 9-0391SBVVT</p> <p><b>Ford 5.4L V8</b><br/>DIAGNOSING VVT CAM PHASER ISSUES</p>            | <b>FORD</b><br>LINCOLN ♦ MERCURY          | 4.6L<br>5.4L ♦ 6.8L | 9-0387<br>9-0391 | 3:09   |         |

## YOUR COMPLETE TIMING AUTHORITY

TECHNICAL SUPPORT: 479-646-1662 Ext. 228  
TECHSUPPORT@CLOYES.COM • CLOYES.COM

© 2022 Cloyes. All Rights Reserved.





# TECH CENTER VIDEOS

THIS IS A CRITICAL ENGINE REPAIR WITH SIGNIFICANT LABOR TIME.

WATCH A SHORT VIDEO FOR INSTRUCTIONS ON YOUR SPECIFIC REPAIR.

**SAVE TIME ♦ SAVE MONEY ♦ REDUCE COMEBACKS**

| THUMBNAIL                                                                                         | VEHICLE PLATFORM                                                                          | ENGINE                                                   | KIT FAMILY                                                            | LENGTH | QR CODE |
|---------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|----------------------------------------------------------|-----------------------------------------------------------------------|--------|---------|
| <p>CLOYES 9-42055A</p> <p><b>GM Gen 3/4</b></p> <p>TIMING CHAIN REPLACEMENT</p>                   | <p><b>GM</b></p> <p>BUICK ♦ CADILLAC</p> <p>CHEVROLET ♦ GMC</p> <p>HUMMER ♦ PONTIAC</p>   | <p>4.8L ♦ 5.3L</p> <p>5.7L ♦ 6.0L</p> <p>6.2L ♦ 7.0L</p> | <p>C-3210</p> <p>C-3220</p> <p>C-3227</p> <p>C-3229</p> <p>9-4205</p> | 5:58   |         |
| <p>CLOYES 9-42015 &amp; 9-42025</p> <p><b>GM 2.0/2.2/2.4L</b></p> <p>TIMING CHAIN REPLACEMENT</p> | <p><b>GM</b></p> <p>BUICK ♦ CHEVROLET</p> <p>GMC ♦ OLDSMOBILE</p> <p>PONTIAC ♦ SATURN</p> | <p>2.0L</p> <p>2.2L ♦ 2.4L</p>                           | <p>9-4201</p> <p>9-4202</p>                                           | 14:31  |         |
| <p>CLOYES 9-07535</p> <p><b>GM 2.8/3.0/3.2/3.6L</b></p> <p>TIMING CHAIN REPLACEMENT DIAGNOSIS</p> | <p><b>GM</b></p> <p>BUICK ♦ CADILLAC</p> <p>CHEVROLET ♦ GMC</p> <p>PONTIAC ♦ SATURN</p>   | <p>2.8L</p> <p>3.0L ♦ 3.6L</p>                           | <p>9-0753</p>                                                         | 7:00   |         |
| <p>CLOYES 9-07535</p> <p><b>GM 2.8/3.0/3.2/3.6L</b></p> <p>TIMING CHAIN REPLACEMENT REPAIR</p>    | <p><b>GM</b></p> <p>BUICK ♦ CADILLAC</p> <p>CHEVROLET ♦ GMC</p> <p>PONTIAC ♦ SATURN</p>   | <p>2.8L</p> <p>3.0L ♦ 3.6L</p>                           | <p>9-0753</p>                                                         | 8:43   |         |
| <p>CLOYES 9-07205</p> <p><b>Nissan 3.5L</b></p> <p>TIMING CHAIN REPLACEMENT</p>                   | <p><b>NISSAN</b></p> <p>INFINITI</p>                                                      | <p>3.5L ♦ 4.0L</p>                                       | <p>9-0719</p> <p>9-0720</p> <p>9-0730</p>                             | 10:12  |         |
| <p>CLOYES 9-43135</p> <p><b>Toyota 2.5/2.7 AR</b></p> <p>TIMING CHAIN REPLACEMENT</p>             | <p><b>TOYOTA</b></p> <p>LEXUS ♦ SCION</p>                                                 | <p>2.0L</p> <p>2.5L ♦ 2.7L</p>                           | <p>9-4313</p>                                                         | 8:15   |         |

## YOUR COMPLETE TIMING AUTHORITY

TECHNICAL SUPPORT: 479-646-1662 Ext. 228  
TECHSUPPORT@CLOYES.COM • CLOYES.COM

© 2022 Cloyes. All Rights Reserved.

